



Glasopeningen overzicht

Afmetingen hebben betrekking op strakke sponningmaten



G1




G2



G3




G4




G5



G6



G7




G8




G9




G10




G11



G12




G13




G19




G22



G27




G51



G53



G54



G55